


- 1 CRUSHER/SCREEN BUILDING
- 2 10,000 TON COAL STOCKPILE
- 3 2,600 TON COAL STOCKPILE
- 4 COAL SAMPLE BUILDING AND CONVEYOR BELT
- 5 42-inch STACKER CONVEYOR
- 6 42-inch CONVEYOR
- 7 54-inch CONVEYOR
- 8 EXCAVATION MATERIAL STOCKPILE
- 9 TOPSOIL STOCKPILE
- 10 SEDIMENT BASIN #9
- 11 RETENTION BASIN #2
- 12 RETENTION BASIN #1
- 13 ROCK DUST BIN
- 14 TRUCK SCALE
- 15 TRUCK LOADOUT
- 16 COAL FEED HOPPER
- 17 BELTLINE TRANSFER POINT
- 18 POWERLINE
- 19 WATER TANK
- 20 AIRSHAFT (16' Dia.)
- 21 TEMPORARY STREAM DIVERSION
- 22 CORRUGATED METAL PIPE (18-inch diam.)
- 23 CORRUGATED METAL PIPE (12-inch diam.)
- 24 3- ENTRY PORTALS
- 25 CATTLE GUARD
- 26 PRIMARY ACCESS ROAD TO FAN
- 27 SUPPLY YARD
- 28 OIL STORAGE
- 29 RECESSED FEEDER
- 30 TRASH PIT
- 31 SKID-MOUNTED SHED

- PERMIT BOUNDARY
- STREAM DIVERSION (UNAFFECTED DRAINAGE)
- BERM
- DISTURBED AREA (SURFACE AFFECTED)
- EXISTING FENCE
- PROPOSED FENCE
- SILT FENCE
- STRAW/HAY BALES
- WIND FENCE (APPROXIMATE)
- CONCRETE BARRIERS (MOVABLE)
- WATER CANNON (PROPOSED LOCATION NORWEST)



THIS STAMP ATTESTS TO THE  
COMPLETION OF REVISIONS 5 AND 6

REV.	DATE	COMMENTS
12/07		FENCE AND STORAGE AREA, AND MAP UPDATE
10/06		ADDED OIL STORAGE, RECESSED FEEDER AND TRASH PIT
02/06		INSIGNIFICANT REVISION (COAL SAMPLE BUILDING)
01/04		MODIFICATION RESPONSE TO BOOM DEFICIENCIES 12/10/03
10/03		MODIFICATION RESPONSE TO BOOM DEFICIENCIES 10-08-03
8/03		ADD 1.5 AC. OF PERMIT AREA OF WHICH 1.0 AC. IS SURFACE DISTURBED AND 4TH EAST PORTAL CONFIGURATION & STRUCTURES WITH AS-BUILT DRAWING

CONSOLIDATION COAL COMPANY			
SESSER ENGINEERING P.O. BOX 566, SESSER, IL 62884			
4 EAST PORTAL SURFACE FACILITIES			
MINE EMERY MINE	DATE 10-16-02	REV. 2-16-06	
CHKD. TDK	SCALE AS NOTED		
APPD.	DRAWING NO. FILE		
DRAWNTDK	SHEET 1 OF 1	PLATE II-3	II-3 4th East Facilities 10/16/06

RECEIVED  
DEC 26 2007  
DIV. OF OIL, GAS & MINING